

Oil Field Environmental Incident Summary

Incident: 20140706143103 **Date/Time of Notice:** 07/06/2014 14:31

Responsible Party: Missouri Basin Well Service Inc

Well Operator: MISSOURI BASIN WELL SERVICE, INC.

Well Name: HYSTAD SWD 1

Field Name: POE

Well File #: 8977

Date Incident: 7/5/2014

Time Incident: 17:59

Facility ID Number:

County: MCKENZIE

Twp: 151

Rng: 100

Sec: 2

Qtr: SW SE

Location Description:

Submitted By: Joshua Staggs

Received By:

Contact Person: Dave Wanner
PO BOX 458
BELFIELD, ND 58622

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	30	Barrels	30	Barrels		
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

Soil and gravel within the Hystad's berm.

Action Taken or Planned:

Retrained driver to always check hatches as part of his duties before unloading material.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 7/6/2014 ***Status:*** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/piping leak, remained on location within the diking, according to the report. NDIC retains oversight.